Alpine Firmware version 1.012_0421 *(May 2022)*

Contents

Firmware Overview

Introduction

Firmware information 2
Requirements and limitations 2

Update Instructions

Precautions 2
Performing the update 2

Introduction

Firmware Information

This Firmware Upgrade is specifically intended for users with the Alpine iLX-W650E. There is one firmware update per unit. If you are unsure if you need this update please contact your nearest Alpine dealer.

Note: The update is not required for Alpine units with Firmware versions 1.012_0421 (May 2022) or higher.

Requirements and limitations

- Windows XP / Windows 7 / Windows 8 / Windows 10
- Formatted USB flash drive with a minimum capacity of 1 GB

Update Instructions

Precautions

- *Do NOT switch off the vehicle / switch off the unit's power nor remove the USB flash drive during the update process.*
- *Do NOT use compressed zip-files for update and do NOT change file names.*
- *Do NOT store any other folders and files on the USB stick*
- *Do NOT operate the Alpine unit whilst updating nor update the Alpine unit while driving*
- *The unit is updated via USB connection. Plug in the USB flash drive into the USB socket of the Alpine unit to initialise the update*

Performing the update

1 Un-zip the downloaded folder into the root directory of the USB flash drive.

2 Turn the vehicle on and plug in the USB flash drive into the USB socket of the Alpine unit.

3 Go to the 'INFORMATION' page via the below menu steps and select 'Firmware Upgrade' from the display.

SETUP → INFORMATION



4 The firmware upgrade will take several minutes to complete. Once the firmware upgrade is complete, the Alpine unit will reset.



5 Following the firmware upgrade, perform a system reset. Go to the 'SYSTEM' page via the below menu steps and select 'Reset'.

SETUP → SYSTEM



6 Go to the 'INFORMATION' page via the below menu steps to confirm the firmware upgrade is successful. See 'System Version: V1.012_0421.

SETUP → INFORMATION → SYSTEM VERSION: V1.012.0421